

ECOFLOW SUCCESS AT

Monte Carlo Resort and Hotel

Monte Carlo
LAS VEGAS RESORT AND CASINO



Location

Las Vegas, NV

Highlights

- 2,992 guestrooms
- 11 nightclubs & lounges
- 10+ restaurants

Problem

The Monte Carlo had serious odor issues within many of their kitchens throughout the hotel, which resulted in complaints from patrons. The kitchens, especially in the D. Vino restaurant, were having grease backups, leading to unpleasant dining experiences.

Ecoflow Solution

Chemsearch FE suggested adding a BIO-Amp™ to the effected grease trap at D. Vino restaurant.

Result

After only two weeks the smell was gone and the grease mat had been eliminated. Since the initial installation, the Monte Carlo has added 8 more BIO-Amps to many of their kitchen areas eliminating backups and odors completely.