

ECOFLOW SUCCESS AT

Hilton Austin



Location

Downtown Austin, TX

Highlights

- Over 450 guestrooms and 16 meeting rooms
- 4 restaurants and a coffee shop

Problem

The Hilton Austin had severe grease buildup within several main lines which caused Hydrogen Sulfide odors and over time, ate through the pipe. They were spending \$13,000 a year on a competitor's product and having their main lines hydro jetted every month, due to high volume of waste leaving their main kitchen and restaurants.

Ecoflow Solution

Chemsearch FE added 2 BIO-Amps™ feeding the main line, which handled all the waste water from their main kitchen, room service and catering.

Result

The installed BIO-Amp's eliminated all of the backups and hydro jetting of the main line. This has saved the Hilton Austin over \$7,000 a year in drain line maintenance costs. Since the initial installation, Chemsearch FE has added nine more units to the building.